



TA1600/2400/3200 V4

Release Notes

Yeastar Digital Technology Co., Ltd.

# Firmware 49.0.0.29

**Date:** January 13, 2026

## Bug fix

- Fixed the registration issue: The registration between the gateway and PBX dropped frequently.

# Firmware 49.0.0.28

**Date:** July 7, 2025

## Improvements

- Added support for connecting the gateway to a self-hosted remote management platform.
- Optimized the auto provisioning feature: Configurations can be directly updated on the gateway without requiring a device reboot. For example, in hotel scenarios, configuration updates take effect immediately upon guest check-in or check-out.

# Firmware 49.0.0.24

**Date:** February 26, 2025

## Bug Fix

- Fixed the auto provisioning issue: When auto provisioning a TA FXS gateway via a domain name, rebooting the gateway from the PBX web interface would fail.

## Firmware 49.0.0.23

**Date: December 11, 2024**

- Fixed the SMS issue: If the password of email address was left blank, the SMTP test couldn't be started.
- Transfer business operations from Xiamen Yeastar Information Technology Co., Ltd to Xiamen Yeastar Digital Technology Co., Ltd..

## Firmware 49.0.0.18

**Date: November 17, 2021**

First Release.

What is new in TA V4 (compared with TA V3):

### Firmware Optimization

- Do not support G723 Codec.
- Optimized Fax feature: TA V4 supports fax processing using software, which can implement multiple fax lines sending and receiving faxes concurrently.
- Added feature of **Loop Current Disconnect** on FXS port.  
When TA gateway detects a loop current on the FXS port, the call on this port will be hung up.

### Hardware Optimization

- Removed DSP module.
- Increased storage volume for Flash and RAM.

Items	TA V3	TA V4
Flash	NAND Flash 512MB	eMMC 4GB
RAM	LPDDR 512MB	DDR4 1GB